


PACSystems™ RX3i

ETHERNET IEC104 SERVICE MODULE

(IC695EIS001)



Introduction

The PACSystems RX3i Ethernet IEC 104 Server Module, catalog number IC695EIS001, implements the IEC 60870-5-104 communications protocol. It permits a PACSystems RX3i controller to be connected to an Ethernet network using a standard TCP/IP connection scheme, allowing an IEC 104 Client to poll data from the Server, as well generate unsolicited communications from the Server back to the Client.

Two auto-sensing 10BaseT/100BaseTX RJ-45 shielded twisted-pair Ethernet ports permit direct connection to either a 10BaseT or 100BaseTX IEEE 802.3 network without an external transceiver. Line, Star and Daisy Chain topologies are supported.

The RX3i Ethernet IEC 104 Server Module hosts the IEC104 Server side protocol on a common RX3i ETM001-Jx module hardware platform. Thus, many of the specifications and behaviors are shared with the ETM001 module including protocol support. IC695EIS001 is an Ethernet-connected module that fits in the RX3i backplane and permits the RX3i to behave as a Server on the IEC104 network. The data exchanges between the EIS001 module and IEC104 Client(s) are configurable, using a single COMMREQ instruction in the ladder logic or Structured Text program.

Module Features

- Supports eight client connection to the RX3i Controller data set specified in the configuration. [RBE supported only on one Client connection associated with a specified port -Refer to GFK-2949B for details]
- Supports Interrogation and RBE for Single Point and Double Point data.
- Supports Interrogation and RBE for Regulated Step.
- Supports Interrogation and Measured data sets for Scaled, normalized, and single precision Float.
- Supports 56-bit IEC 60870-5-104 time format, with the default being 56-bit time format.
- Supports *Time Set*, and query of the RX3i Controller CPU Clock in UTC time.
- *Cause of Transmission* size is two octets.

RX3i Interface specifications:

- Up to four EIS001 per RX3i, as allowed by available power and slots.
- Module can be installed in any available RX3i main rack I/O slot.
- Module supports insertion into and removal from an RX3i backplane which is under power.
- Firmware upgrade through RX3i CPU using WinLoader software utility.

Upgrade Kit: 41G2076-MS10-000-A4

This combines a compatible Ethernet Firmware Upgrade Kit and IEC 104 Server Firmware Kit in one package.

Hardware ID	Catalog Number	Board ID	Board Revision
IC695EIS001 Ethernet IEC 104	IC695EIS001-DD	EX4B1	41G1299-BA10-000-D3
Ethernet TCP Firmware ID	Version: 6.41 Build 09A1		
Ethernet Boot Firmware ID	Version: 3.71 Build 43A1		
Ethernet Toolkit Plugin3 - IEC 104 Server License	N/A		
Ethernet Toolkit Plugin2 - IEC 104 Server Application	Version: 130 (0xC142)		
Ethernet Programmable Parts	Part ID	Revision	
	PLD	44I725580-1401B	
	Flash Memory - U3	41G2040-FW10-000-A4	
	Flash Memory - U4	41G2040-FW10-001-A4	
	Microcontroller 405GPR –U66	41G1911-FW10-000-A0	

Release History

Catalog Number	Firmware Version	Date	Comments
IC695EIS001CA-GD IC695EIS001-GD	Firmware 6.41/1.30	Oct 2021	The product's labels have been updated to show compliance with new certifications. For updated certifications, please refer to https://emerson-mas.force.com/communities/en_US/Article/Certifications-and-Agency-Approvals-Landing-Page .
IC695EIS001-ED	Firmware 6.41/1.30	Sep 2019	Following Emerson's acquisition of this product, changes have been made to apply appropriate branding and registration of the product with required certification agencies. No changes to material, process, form, fit or functionality.
IC695EIS001-DD	Firmware 6.41/1.30	Oct 2017	This hardware release addresses a component obsolescence issue. There are no changes to form, fit, or function.
IC695EIS001-CE	Firmware 6.41/1.40	Aug 2017	This firmware provides enhancement to enable Report by Exception of analog data without time stamp through ASDU13 spontaneously instead of ASDU36. It also fixes issue where IEC104 Master reads incorrect data for transient period (~ 100ms to 120ms) from EIS module (IEC104 server) intermittently over long duration of operation.
IC695EIS001-CD	Firmware 6.41/1.30	Apr 2016	This firmware enables multiple IEC 104 Clients connections to the IEC 104 Server module (Max 8 Connections). It also provides a mechanism to shift RBE (Report by Exception) data during runtime, on one specific Client connection associated with a specified Port Number using COMMREQ (Communication request) in the Controller logic.
IC695EIS001-CC	Firmware 6.40 /1.20 Boot 3.71	Feb 2016	This Firmware fixes issue with module going unexpectedly in firmware update mode, as part of the Web upgrade kit. An enhancement was made to prevent the module from becoming unresponsive and requiring a power cycle if it was subjected to heavy network storm traffic.

IC695EIS001-BB	1.10	Apr 2015	The Memory Address Translation feature added in this release supports Unambiguous (Unique) Object Addressing as required by some legacy SCADA clients (like CPELE/SAGE). Refer to PACSystems RX3i Ethernet IEC 104 Server Module IC695EIS001 User Manual, GFK-2949A or later for details.
IC695EIS001-AA	1.00	Dec 2014	Initial release.

Functional Compatibility

Subject	Minimum Version Required
Programmer Version Requirements	PAC Machine Edition Logic Developer Release 8.5 SIM 9 or later.
Ethernet Firmware Version Requirements	Ethernet (ETM001-jx) Primary Firmware Release 6.30 (Build: 41A1) Ethernet (ETM001) Boot Firmware Release 3.60 (Build: 45A1)
Module Hardware Requirements	The newly released EIS001 firmware is compatible with original hardware (IC695EIS001-AA) and with new hardware (IC695EIS001-BB). <i>Note:</i> It is not compatible with IC695ETM001 hardware.
RX3i CPU version Requirements	CPU320/CPU315 Primary Firmware Release 8.05 CPE310/CPE305 Primary Firmware Release 8.05 CRU320 Primary Firmware Release 8.05 CPE330 Primary Firmware Release 8.45

Problems Resolved by this Revision

None

New Features and Enhancements

Subject	Description
Multiple Client connection support	This firmware enables multiple IEC 104 Clients connections to the IEC 104 Server module (Max 8 Connections). In case of multiple Client Connections, IEC 104 Server module sends RBE (Report by Exception) data to only one Client connection with designated & configured port (typically #2404) by default. The IEC 104 Server module does not send RBE data to other client connections. However, this RBE (Data) can be shifted to any other Client connections associated with a specified port during Runtime through a special COMMREQ#1242. This firmware provides a mechanism to shift RBE (Report by Exception) data during runtime, on one specific Client connection associated with a specified Port Number using COMMREQ (Communication request) in the Controller logic. Refer to the GFK-2949B for configuration and other details of the feature.

Restrictions and Open Issues

None

Additional Information

PACSystems RX3i User Manuals PACSystems RX7i & RX3i TCP/IP Ethernet Communications User Manual	GFK-2224
PACSystems TCP/IP Ethernet Communications Station Manager Manual	GFK-2225
PACSystems RX3i Ethernet IEC 104 Server Module IC695EIS001 Quick Start Guide	GFK-2948
PACSystems RX3i Ethernet IEC 104 Server Module IC695EIS001 User Manual	GFK-2949
PACSystems RX3i Ethernet Module IC695ETM001 IPI	GFK-2332
PACSystems RX3i Ethernet IEC 104 Server Module IC695EIS001 IPI	GFK-2947

User manuals, product updates and other information sources are available on our support website,

<https://www.emerson.com/Industrial-Automation-Controls/support> under Controllers and IO, RX3i Controllers.

Operational Notes

Subject	Description
Station Manager unresponsive	Station Manager can become unresponsive when there is high polling rate, or high point load on the EIS001 module.
Use of Redundant IP with the EIS001 in a CRU application	IEC 104 is a connection oriented protocol, and during a role switch of a CRU controller the MAC Address of the Redundant IP will change, typically causing TCP/IP connections to be disrupted, then reconnected. It is likely that an IEC 104 Client with a connection to an EIS001 module in this type of configuration will experience a connection change, causing the IEC 104 data to be temporarily unavailable.
Use of SOE parameter with the EIS001 in a CRU application	It is not recommended that SOE be used in CRU applications, as, on a role switch, the EIS001 module can lose buffered events, but has no retention or RMX Sync.
IEC 104 Data During Role Switch with EIS001 Modules in a CRU Application	Whenever a role switch occurs in a redundant application, a bump in IEC 104 data will likely be observed at the connected IEC 104 Client. This depends on the client tolerance and AUP File parameters (<i>wkal_idle</i> , <i>wkal_cnt</i> , <i>wkal_intvl</i>). These parameters need to be adjusted to accommodate for the intervening network hops, in order to achieve optimized performance during role switching.
Use of Option Bit 0 in COMMREQ [74] use with Point Push	When option bits settings are configured to accept Point Push data only when a connection exists (i.e. Bit#0 of <i>mComreq_Setup</i> [74] = 1), be aware of the following latency issue. After the IEC 104 client connection is disrupted (cable removed or network otherwise disrupted), the Point Push data will continue to be accepted for approximately 100 ms and will be buffered. This is due to the inherent latency in detecting the disrupted connection state.
Binary ADSUs Spontaneous Event Generation	For Binary ADSUs (Single-Point and Double-Point), Spontaneous events are not reported back to the IEC 104 Client, when these points are changed via the connected IEC 104 Client. However, Spontaneous events are generated when these points are changed via an internal mechanism in the RX3i controller, such as via program logic.
Use of Report by Exception (RBE) with EIS001 Module in a CRU Application	It is not recommended that a Client use RBE (Report by Exception) data with CRU applications, as, on a role switch, there can be loss of data for a short duration.
Synchronizing the LSI Bits between CRU CPUs	In redundancy applications, synchronizing the LSI (LAN Status Interface) bits is not recommended, as it may cause the ST block that contains the COMMREQ setup to execute prematurely on a role switch. Independent bits, or Symbolic bits, should be used for the LSI data.

General Contact Information

Home link: <http://www.emerson.com/industrial-automation-controls>
Knowledge Base: <https://www.emerson.com/industrial-automation-controls/support>

Technical Support

Americas

Phone: 1-888-565-4155
1-434-214-8532 (If toll free option is unavailable)

Customer Care (Quotes/Orders>Returns): customercare.mas@emerson.com
Technical Support: support.mas@emerson.com

Europe

Phone: +800-4444-8001
+420-225-379-328 (If toll free option is unavailable)
+39-0362-228-5555 (from Italy - if toll-free 800 option is unavailable or dialing from a mobile telephone)

Customer Care (Quotes/Orders>Returns): customercare.emea.mas@emerson.com
Technical Support: support.mas.emea@emerson.com

Asia

Phone: +86-400-842-8599
+65-6955-9413 (All other Countries)

Customer Care (Quotes/Orders>Returns): customercare.cn.mas@emerson.com
Technical Support: support.mas.apac@emerson.com

Any escalation request should be sent to mas.sfdcescalation@emerson.com

Note: If the product is purchased through an Authorized Channel Partner, please contact the seller directly for any support.

Emerson reserves the right to modify or improve the designs or specifications of the products mentioned in this manual at any time without notice. Emerson does not assume responsibility for the selection, use, or maintenance of any product. Responsibility for proper selection, use, and maintenance of any Emerson product remains solely with the purchaser. s

© 2022 Emerson. All rights reserved. Emerson Terms and Conditions of Sale are available upon request. The Emerson logo is a trademark and service mark of Emerson Electric Co. All other marks are the property of their respective owners.

