


PACSystems™ RX3i

DNP3 OUTSTATION MODULE (IC695EDS001)




Introduction

The PAC Systems RX3i DNP3 Outstation Module IC695EDS001 is an Ethernet-connected module which fits in the RX3i backplane and permits the RX3i to behave as an Outstation on the DNP3 network, where it may interact with up to eight DNP3 masters.

Module features include:

- Two auto-sensing RJ-45 Ethernet ports with LED indicators
 - Connects via Ethernet at 10BaseT or 100BaseTX
 - Internal network switch with Auto-negotiate, Sense, Speed, and crossover detection
 - Supports Linear (daisy-chained) and Star network configurations
 - TCP/IP and LLA protocols supported
 - One Ethernet MAC Address and one IP Address per module
 - Time synchronization to SNTP Time Server
 - Recessed Ethernet Restarts pushbutton to manually restart the Ethernet firmware without power-cycling the module.
- Dedicated RS-232 Station Manager Port for network supervision
- LED behavior same as ETM001-Jx
- DNP3 configuration via a single COMMREQ command
 - Data exchanges up to 12,072 points and 24,000 events supported
 - Eight DNP3 Objects supported: DI, DI w/time, DO, DO w/time, CROB, analog output values, time setting, and class polls
 - Multiple RX3i memory types may be utilized for DNP3 data exchange
 - Binary DI/DO
 - Analog (32-bit signed, 16-bit signed, or single-precision floating point)
 - Supports unsolicited data communications with DNP3 Master
 - Master IP Address and LLA Address White listing
- Compatible with those RX3i CPUs as noted on page 4, including redundant controllers
 - Up to 4 EDS001 per RX3i, as allowed by available power and slots
 - Module can be installed in any available RX3i main rack I/O slot
 - Module supports insertion into and removal from an RX3i backplane which is under power.
 - Firmware upgrade via RX3i CPU using Win Loader software utility

Figure 1: Module Features



Upgrade Kit: 41G2060-MS10-000-A5

This combines a compatible Ethernet Firmware Upgrade Kit and DNP3 Outstation Firmware Kit in one package.

Hardware ID	Catalog Number	Board ID	Board Revision
IC695EDS001 Ethernet DNP3	IC695EDS001-DF	EX4B1	41G1299-BA10-000-D3
Ethernet TCP Firmware ID	Version: 6.43 Build 29A1		
Ethernet Boot Firmware ID	Version: 3.71 Build 43A1		
Ethernet Toolkit Plugin3 -DNP3 Slave License	N/A		
Ethernet Toolkit Plugin2 -DNP3 Slave Application	Version: 150 (0xD303)		
Ethernet Programmable Parts	Part ID	Revision	
	PLD	44I725580-1401B	
	Flash Memory - U3	41G1299-FW10-000-A4	
	Flash Memory - U4	41G1299-FW10-001-A4	
	Microcontroller 405GPR – U66	41G1911-FW10-000-A0	

Release History

Catalog Number	Firmware Version	Date	Comments
IC695EDS001-FF	Firmware 6.43 /1.50	Oct 2020	Change in product manufacturing location. No changes to material, process, form, fit or functionality.
IC695EDS001-EF	Firmware 6.43 /1.50	Sep 2019	Following Emerson's acquisition of this product, changes have been made to apply appropriate branding and registration of the product with required certification agencies. No changes to material, process, form, fit or functionality.
IC695EDS001-DF	Firmware 6.43 /1.50	Aug 2018	Firmware version 6.43 provides the following enhancements: Security enhancements to harden the product against an attacker. Improvements to Ethernet configuration to improve Ethernet performance. Enhancements to improved network storm survivability Firmware version 1.50 provides several open problem resolutions, see "Problems Resolved by this Revision" section for details in addition, it also adds configuration parameter for enabling Extended DNP3 Keep Alive Timeout. This, when enabled, allows DNP3 sessions to ride through communications disturbances of up to 60 seconds in length.
IC695EDS001-DE	Firmware 6.41 /1.40	Mar 2017	This hardware release addresses a component obsolescence issue. There are no changes to form, fit, or function.
IC695EDS001-CE	Firmware 6.41 /1.40	Feb 2016	An enhancement was made to prevent the module from becoming unresponsive and requiring a power cycle if it was subjected to heavy network storm traffic.

Catalog Number	Firmware Version	Date	Comments
IC695EDS001-CD	Firmware 6.31 /1.30 Boot 3.71	Dec 2015	<p>This hardware release addresses an issue identified, where the module can unexpectedly go into firmware update mode (Ethernet OK, LAN OK, and Log Empty LEDs blink in unison). While in firmware update mode, the module is unresponsive to Ethernet traffic. There are no changes to form, fit, or function.</p> <p>This Firmware provides enhancements to configure the Event Buffer size separately for Digital Inputs (BI – Binary Inputs and BO – Binary Output status) and Analog Inputs (AI – Analog Inputs and AOS – Analog Output status) and support specific DNP3 object variations. This also fixes issue with module going unexpectedly in firmware update mode, as part of the Web upgrade kit.</p>
IC695EDS001-BC	1.20	Jul 2015	This firmware release fixes the issue related to IIN Bits indicating Class1 and Clas2 Data Available status to DNP3 Master. The firmware also corrects the control code for Close and Trip Control (Close=101) and (Trip =110) in the CROB Control DWORD to be consistent with description in User manual –Section 6.9.2.
IC695EDS001-BB	1.10	Apr 2015	<p>Added a feature to support different control codes like PULSE ON/OFF, CLOSE, TRIP and LATCH ON/OFF for the CROB Control objects. This also enhanced the Quality functionality for ensuring that events are generated when quality is offline, and appropriate quality status is updated.</p> <p>This hardware release addresses a component obsolescence issue. There are no changes to form, fit, or function.</p>
IC695EDS001-AA	1.00	Oct 2014	Initial release.

Functional Compatibility

Subject	Minimum Version Required
Programmer Version Requirements	PAC Machine Edition Logic Developer Release 8.5 SIM 7 or later.
Ethernet Firmware Version Requirements	Ethernet (ETM001-Jx) Primary Firmware Release 6.30 (Build: 41A1) Ethernet (ETM001) Boot Firmware Release 3.60 (Build: 45A1)
Module Hardware Requirements	The newly-released EDS001 firmware is compatible with original hardware (IC695EDS001-AA) and with new hardware (IC695EDS001-BB). Note: It is not compatible with IC695ETM001 hardware.
RX3i CPU version Requirements	CPU320/CPU315 Primary Firmware Release 8.05 CPE310/CPE305 Primary Firmware Release 8.05 CRU320 Primary Firmware Release 8.05 CPE330 Primary Firmware Release 8.45

Problems Resolved by this Revision

None

New Features and Enhancements

None

Restrictions and Open Issues

Subject	ID code	Description
Byte Swap Error	00259269	During long runs for Object type 30, the Controller reference memory data reported in response to a poll request from the Master was intermittently observed to contain corrupted data. Data was being swapped between the high and low bytes.
White Listing of Master LLA	DE1839	The EDS001 module allows the establishment of a white list of allowed connections, both TCP/IP and LLA Master Station addresses. The parameters for this feature are such that they can be enabled independently. However, LLA white listing is to be used with TCP/IP white listing, not by itself.
Multiple role switching causing 2-5 Blink code when EDS is configured for "Fixed Event Buffer" in an HSB system	DE4879	<p>During multiple Role switches in an HSB system, the EDS module(s) for which the DNP3 COMMREQ Application is configured as "Linear Fixed Buffer" for event buffering goes to 2-5 Blink code exception.</p> <p>It is recommended to use "Circular Event Buffer" for event buffering, when used in HSB system with Redundant IP. The Option Parameter Word [17] Bit 12 in the COMMREQ configuration should be set to '1' to enforce the Circular event buffer, avoiding this issue.</p>

Operational Notes

Subject	Description
Station Manager unresponsive	Station Manager can become unresponsive when there is high polling rate, or high point load on the EDS001 module.
Use of Redundant IP with the EDS001 in a CRU application	DNP3 is a connection-oriented protocol, and during a role switch of a CRU controller the MAC Address of the Redundant IP will change, typically causing TCP/IP connections to be disrupted, then reconnected. It is likely that a DNP3 Master with a connection to an EDS001 module in this type of configuration will experience a connection change, causing the DNP3 data to be temporarily unavailable.
Use of SOE parameter with the EDS001 in a CRU application	It is not recommended that SOE be used in CRU applications, as, on a role switch, the EDS001 module can lose buffered events, or hold them for a future role switch.
Use of Master Set DNP3 Unsolicited mode with the EDS001 in a CRU application	It is not recommended that a Master use unsolicited mode with CRU applications, as, on a role switch, the EDS001 module can lose buffered events, or hold them for a future role switch. Also, on a role switch, the Master may not know to reissue the Unsolicited Enable command to the EDS001 module.
Synchronizing the LSI bits between CRU CPUs	In redundancy applications, synchronizing the LSI (LAN Status Interface) bits is not recommended, as it may cause the ST block that contains the COMMREQ setup to execute prematurely on a role switch. Independent bits, or Symbolic bits, should be used for the LSI data.
Using Point Push with Analog Data	Analog points, when pushed, will take on the default variance size specified by the COMMREQ parameter.

Additional Information

PAC Systems RX3i User Manuals

PAC Systems RX7i & RX3i TCP/IP Ethernet Communications User Manual	GFK-2224
PACSystems TCP/IP Ethernet Communications Station Manager Manual	GFK-2225
PACSystems RX3i DNP3 Outstation Module IC695EDS001 User Manual	GFK-2911
PACSystems RX3i DNP3 Outstation Module IC695EDS001 Quick Start Guide	GFK-2912
PACSystems RX3i Ethernet Module IC695ETM001 IPI	GFK-2332
PACSystems RX3i Ethernet DNP3 Outstation Module IC695EDS001 IPI	GFK-2333

Technical Support & Contact Information

Home link: <http://www.Emerson.com/Industrial-Automation-Controls>

Knowledge Base: <https://www.emerson.com/Industrial-Automation-Controls/support>

Note: If the product is purchased through an Authorized Channel Partner, please contact the seller directly for any support.

Emerson reserves the right to modify or improve the designs or specifications of the products mentioned in this manual at any time without notice. Emerson does not assume responsibility for the selection, use or maintenance of any product. Responsibility for proper selection, use and maintenance of any Emerson product remains solely with the purchaser.

© 2019 Emerson. All rights reserved.

Emerson Terms and Conditions of Sale are available upon request. The Emerson logo is a trademark and service mark of Emerson Electric Co. All other marks are the property of their respective owners.

