

# **PAC Productivity Suite**

**Version 10.1**

# Contents

PAC Product Information .....	<b>1</b>
Revision History.....	<b>1</b>
Release Notes .....	<b>1</b>
PAC Productivity Suite .....	<b>2</b>
Functional Compatibility .....	2
Problems Resolved by this Release.....	2
New Features.....	3
Dropped Features.....	3
Related Documents .....	<b>4</b>
Additional Support .....	<b>4</b>
General Contact Information .....	<b>5</b>
Technical Support.....	<b>5</b>

## Warnings and Caution Notes as Used in this Publication

### **WARNING**

Warning notices are used in this publication to emphasize that hazardous voltages, currents, temperatures, or other conditions that could cause personal injury to exist in this equipment or may be associated with its use.

In situations where inattention could cause either personal injury or damage to equipment, a Warning notice is used.

---

### **CAUTION**

Caution notices are used where equipment might be damaged if care is not taken.

---

**Note:** *Notes merely call attention to information that is especially significant to understanding and operating the equipment.*

These instructions do not purport to cover all details or variations in equipment, nor to provide for every possible contingency to be met during installation, operation, and maintenance. The information is supplied for informational purposes only, and Emerson makes no warranty as to the accuracy of the information included herein. Changes, modifications, and/or improvements to equipment and specifications are made periodically and these changes may or may not be reflected herein. It is understood that Emerson may make changes, modifications, or improvements to the equipment referenced herein or to the document itself at any time. This document is intended for trained personnel familiar with the Emerson products referenced herein.

Emerson may have patents or pending patent applications covering subject matter in this document. The furnishing of this document does not provide any license whatsoever to any of these patents.

Emerson provides the following document and the information included therein as-is and without warranty of any kind, expressed or implied, including but not limited to any implied statutory warranty of merchantability or fitness for particular purpose.

# PAC Product Information

<b>Product</b>	<b>Version</b>
PAC Productivity Suite	<b>10.1</b>
PAC Machine Edition Logic Developer QP+ (View / PC)	<b>10.1</b>
PAC Change Management Server Client Scheduler Engine	<b>10.1</b>
CIMPLICITY	<b>2022</b>

## Revision History

<b>Version</b>	<b>Date</b>	<b>Description</b>
Version 10.1	Feb 2023	Updated for the release of PME v10.1, PPS v10.1, PCM v10.1, and View and Control
Version 10.0	May 2022	Update to documentation to clarify CPE3XX support.
Version 10.0	Apr 2022	Initial Release

## Release Notes

When upgrading from Versions of PAC Machine Edition older than 10.0, your PME window settings and system options may be reset.

It is important to set the EGD Management Tool and EGD PowerTool to “run as administrator.”

## Known Issues

It has been observed that running the CIMPLICITY Object Builder can result in error messages indicating that the path to ProducedData.xml cannot be found or that it doesn't exist.

# PAC Productivity Suite

## Functional Compatibility

Subject	Description
CPE200 Series require PME 10 or higher	With PME 10.1, PME 9.8 formats cannot be saved.
Non-Supported Operating Systems	Dropped support for the following operating systems: <ul style="list-style-type: none"> <li>• Microsoft® Windows® XP</li> <li>• Microsoft® Windows® Server 2003</li> <li>• Microsoft® Windows® Server 2008</li> <li>• Microsoft® Windows® 7</li> </ul>
Supported Operating Systems	<ul style="list-style-type: none"> <li>• Microsoft® Windows® 10</li> <li>• Microsoft® Windows® 10 IoT Enterprise</li> <li>• Microsoft® Windows® 11</li> <li>• Microsoft® Windows® Server 2016</li> <li>• Microsoft® Windows® Server 2019</li> </ul>

## Problems Resolved by this Release

PAC Productivity Suite 10.1 fixed the following defects:

Resolved Problem	Defect Code	Resolution
EGD Management Tool displays CPE based systems as unhealthy	DE5905	Updated EGD management tool so that it doesn't show CPE based systems as unhealthy.
Missing Restore menu option for EGD restoration	DE5946	Restore is now included with EGD
PME cannot disconnect from a PLC when license is lost	DE7148	License check was modified so that ME can disconnect from a PLC when the license is lost/returned.
Safety Enhancement Request - EGD timeout default is zero. This means there is no timeout.	DE7779	Added an option under EGD to allow consumer to set a different timeout default value.
EGD Adapter Change after CPU upgrade to CPE	DE8006	Maintained previous CPUs LAN A and LAN B Adapters values. After replacing CPU, used previous CPUs maintained values and calculated index of those values from adapter container. Set those calculated indexes to new CPU.
Status Address will change once ETM module is replaced with -Kxxx version	DE8007	Before deleting an IC695ETM001 module, the "Status Address" value was stored in a variable. After adding IC695ETM001-Kxxx module, the above step's stored "Status Address" value is stored in this module.
Removing empty process folders	DE8942	Added condition to check folder is empty and marked empty folder to deletable

Resolved Problem	Defect Code	Resolution
Error in Feedback Zone does not match the Error Displayed on the Companion	DE9101	Corrected error messaging in Feedback Zone.
Ladder logic "by-pass" lines	DE9660	Ladder logic has been updated
Is it possible to disable outputs automatically when downloading	US39881	An option was added to allow "Run Output Disabled" mode remotely
PPS 3.8 of Zilor - CIMPLICITY/PDS SRTP Proficy Driver Server	US43393	PDS was removed from the PPS installer. PDS can be obtained and licensed by contacting GE Digital. It is not an Emerson product.

## New Features

PAC Productivity Suite 10.1 makes various improvements on the following:

New Feature	Description
Upgraded to CIMPLICITY 2022 Sim 4	Upgraded CIMPLICITY 10 to CIMPLICITY 2022 Sim 4. CIMPLICITY 2022 features a revamped "help" system along with other features.
Upgraded Engineering Workstation Logic Developer	Engineering Workstation Logic Developer has been updated to leverage PME 10.1 features.
Added Leased License Support	PPS software now supports leased licensing.

## Dropped Features

PAC Productivity Suite 10.1 dropped the following:

Dropped Feature	Description
Proficy Driver Server removed from the PPS installer	Proficy Driver Server is not part of PPS and was removed from the installer. Proficy Driver Server is a GE Digital product and requires a GE license.

# Related Documents

For additional information about the Ethernet Interface Module, refer to the following publications:

<i>PAC Change Management for Machine Edition – Getting Started</i>	GFK-1779
<i>PAC Machine Edition - View™ and PC Control – Getting Started Guide</i>	GFK-1868
<i>PAC Machine Edition - Logic Developer – PLC – Getting Started Guide</i>	GFK-1918
<i>Entitlement and License Manager User Manual</i>	GFK-3104
<i>Emerson Legacy Licensing Guide</i>	GFK-3107
<i>PAC Productivity Suite Configuration Guide</i>	GFK-3134
<i>PAC Productivity Suite Installation, Operation, and Maintenance Manual</i>	GFK-3136
<i>PAC Productivity Suite Application Setup and Configuration Guide</i>	GFK-3137
<i>PAC Machine Edition Version 10.1 IPI</i>	GFK-3244
<i>PAC System Requirements</i>	GFK-3245
<i>PAC License Server Administrator User Manual</i>	GFK-3247
<i>PAC Change Management 10.1 IPI</i>	GFK-3258

# Additional Support

For support and information, visit Emerson's support link located at the end of this document. The files for this manual and other related documentation are available there. Additional region- and language-specific websites and telephone numbers are found there as well.

# General Contact Information

Home link: <http://www.emerson.com/industrial-automation-controls>

Knowledge Base: <https://www.emerson.com/industrial-automation-controls/support>

## Technical Support

### Americas

Phone: 1-888-565-4155  
1-434-214-8532 (If toll free option is unavailable)

Customer Care (Quotes/Orders>Returns): [customercare.mas@emerson.com](mailto:customercare.mas@emerson.com)  
Technical Support: [support.mas@emerson.com](mailto:support.mas@emerson.com)

### Europe

Phone: +800-4444-8001  
+420-225-379-328 (If toll free option is unavailable)

Customer Care (Quotes/Orders>Returns): [customercare.emea.mas@emerson.com](mailto:customercare.emea.mas@emerson.com)  
Technical Support: [support.mas.emea@emerson.com](mailto:support.mas.emea@emerson.com)

### Asia

Phone: +86-400-842-8599  
+65-6955-9413 (All other Countries)

Customer Care (Quotes/Orders>Returns): [customercare.cn.mas@emerson.com](mailto:customercare.cn.mas@emerson.com)  
Technical Support: [support.mas.apac@emerson.com](mailto:support.mas.apac@emerson.com)

Any escalation request should be sent to: [mas.sfdcescalation@emerson.com](mailto:mas.sfdcescalation@emerson.com)

**Note:** If the product is purchased through an Authorized Channel Partner, please contact the seller directly for any support.

Emerson reserves the right to modify or improve the designs or specifications of the products mentioned in this manual at any time without notice. Emerson does not assume responsibility for the selection, use or maintenance of any product. Responsibility for proper selection, use and maintenance of any Emerson product remains solely with the purchaser.

© 2022 Emerson. All rights reserved.

Emerson Terms and Conditions of Sale are available upon request. The Emerson logo is a trademark and service mark of Emerson Electric Co. All other marks are the property of their respective owners.

